



US00D892972S

(12) **United States Design Patent** (10) **Patent No.:** **US D892,972 S**
Mullen et al. (45) **Date of Patent:** **** Aug. 11, 2020**

(54) **SUMP PLATE** D223,829 S * 6/1972 Cook D23/261
3,784,011 A * 1/1974 Ward B01D 29/055
210/167.03
(71) Applicant: **Best Management Products Inc.,** D308,461 S * 6/1990 Hosea A47G 19/06
Lyme, CT (US) D7/507
(72) Inventors: **T. J. Mullen,** Essex, MD (US); D329,380 S * 9/1992 Hazlett D9/434
Matthew White, East Haddam, CT D354,670 S * 1/1995 Simon D8/314
(US) 5,733,444 A * 3/1998 Johnson E03F 5/0401
210/163
D397,667 S * 9/1998 White D12/223
(Continued)

(73) Assignee: **Best Management Products Inc.,**
Lyme, CT (US)

(**) Term: **15 Years**

(21) Appl. No.: **29/669,804**

(22) Filed: **Nov. 12, 2018**

(51) **LOC (12) Cl.** **23-01**

(52) **U.S. Cl.**
USPC **D23/206**

(58) **Field of Classification Search**
USPC D23/206, 268, 261; D15/5; D8/16, 18,
D8/19, 349, 350, 382; D7/507, 566, 701,
D7/620, 397; D12/223, 411
CPC E03F 5/14; E03F 5/16; E03F 10/14; E03F
7/06; E03F 2201/00; E03F 2201/10;
A47F 7/28; A47F 7/0064; B60R 13/0861;
B03B 5/28; B03B 5/30; B03B 5/40;
B03B 5/44; B03B 5/50; E21B 27/005;
E21B 21/002

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D34,980 S * 8/1901 Higgins D15/5
D57,561 S * 4/1921 Wilson D8/19
1,985,738 A * 12/1934 Mullin E03F 5/14
210/299
2,921,690 A * 1/1960 Smith A47F 7/285
211/73
D191,184 S * 8/1961 Scholz D23/261

OTHER PUBLICATIONS

BMP Inc, TP18-90, (Site visited Jun. 12, 2020), BMP Inc website,
URL:<<https://www.bmpinc.com/products/>> (Year: 2020).*

(Continued)

Primary Examiner — Eric L Goodman

Assistant Examiner — Mark T Philipps

(74) *Attorney, Agent, or Firm* — Murtha Cullina LLP


(57) **CLAIM**

The ornamental design for a sump plate, as shown and described.

DESCRIPTION

FIG. 1 is a side perspective view of a sump plate according to an embodiment of the invention;
FIG. 2 is a front view of the sump plate shown in FIG. 1;
FIG. 3 is a back view of the sump plate shown in FIG. 1;
FIG. 4 is a right side view of the sump plate shown in FIG. 1;
FIG. 5 is a left side view of the sump plate shown in FIG. 1;
FIG. 6 is a top view of the sump plate shown in FIG. 1; and,
FIG. 7 is a bottom view of the sump plate shown in FIG. 1.
The features shown in broken lines in the drawing depict the environmental subject matter and form no part of the claimed design.

1 Claim, 4 Drawing Sheets



(56)

References Cited

U.S. PATENT DOCUMENTS

D398,283 S * 9/1998 Miller D12/223
 6,122,951 A * 9/2000 Arbesman B21K 1/00
 72/377
 D436,516 S * 1/2001 Lambacher D8/349
 D483,651 S * 12/2003 Sander D8/349
 D523,537 S * 6/2006 Howard D23/261
 H2203 H * 10/2007 Borchardt D8/396
 D556,214 S * 11/2007 Fretwell D15/5
 D636,802 S * 4/2011 Kawai D15/147
 D659,714 S * 5/2012 Gieske D15/5
 8,277,645 B2 * 10/2012 Jarvis, Jr. E03F 1/00
 210/131
 8,579,133 B2 * 11/2013 Marcus A61J 9/08
 215/11.6
 8,663,466 B2 * 3/2014 Braunwarth B01D 21/0003
 210/170.03
 8,763,195 B2 * 7/2014 Bouix A46B 17/06
 15/105
 9,057,189 B2 * 6/2015 Flury E03F 5/14
 D734,997 S * 7/2015 Leblanc D7/701
 D738,807 S * 9/2015 Lochala D12/223
 9,322,155 B2 * 4/2016 Jarvis E03F 5/0404
 D793,455 S * 8/2017 Atterbury D15/17
 D798,908 S * 10/2017 Clark D15/5
 D808,504 S * 1/2018 Janesky D23/261

D817,728 S * 5/2018 Brown D7/701
 D841,695 S * 2/2019 Pirolo D15/5
 D870,524 S * 12/2019 Burch, V D8/16
 10,655,318 B2 * 5/2020 Paivinen B01D 21/0033
 2009/0208289 A1 * 8/2009 Flury E03F 5/046
 405/94
 2010/0107519 A1 * 5/2010 Reaveley E04H 9/02
 52/167.4
 2010/0147752 A1 * 6/2010 Jarvis, Jr. E03F 5/14
 210/123
 2019/0078311 A1 * 3/2019 Paivinen B01D 21/0003
 2020/0109548 A1 * 4/2020 Zock B01D 29/05

OTHER PUBLICATIONS

BMP Inc, TP12-90 spec sheet, (created Jan. 24, 2019), BMP Inc website, URL:<<https://www.bmpinc.com/wp-content/uploads/2019/03/TP12-90.pdf>> (Year: 2019).*
 SWS, Sediment Control, (posted Oct. 29, 2019), SWS magazine online, URL:<<https://www.estormwater.com/sediment-control/sediment-control-1>> (Year: 2019).*
 Front Runner, Toyota Land Cruiser 79 Sump Guard—by Front Runner, (site visited Jun. 12, 2020), Front Runner Outfitters Website, URL:<<https://www.frontrunneroutfitters.com/en/au/front-runner-ump-guard-toyota-land-cruiser-79.html>> (Year: 2020).*

* cited by examiner

FIG. 1




FIG. 2




FIG. 3




FIG. 4



FIG. 5




FIG. 6



FIG. 7

