



US00D362185S

# United States Patent [19]

[11] Patent Number: **Des. 362,185**

Ramsey

[45] Date of Patent: **\*\* Sep. 12, 1995**

[54] **STATUS INDICATING AND TAMPER EVIDENT CLOSURE**

[76] Inventor: **Joseph W. Ramsey**, 11 Great Meadow La., East Hanover, N.J. 07936

[\*\*] Term: **14 Years**

[21] Appl. No.: **20,128**

[22] Filed: **Mar. 17, 1994**

[52] U.S. Cl. .... **D9/438**

[58] Field of Search ..... **D7/317, 629; D9/434-436, 438, 443, 445-447, 449, 454; 215/216, 232, 237, 253, 246, 251; 220/266, 268, 344, 359, 711, 713, 715**

[56] **References Cited**

**U.S. PATENT DOCUMENTS**

D. 56,596	11/1921	Hyatt	.....	D9/452
D. 133,643	9/1942	Simmons	.....	D9/435
D. 182,779	5/1958	Tupper	.....	D9/439
D. 200,820	4/1965	Blakslee	.....	D9/443
D. 200,884	4/1965	Hart	.....	D9/438
D. 292,967	12/1987	Gagnon	.....	D9/439
D. 311,620	10/1990	Rose	.....	D9/435
1,026,282	5/1912	Schmitt	.....	D9/438 X
1,767,512	6/1930	Cohoe	.....	215/246
2,814,404	11/1957	Towns	.....	215/320
3,197,057	7/1965	Weitzner	.....	D9/438 X

3,281,001	10/1966	Stuart	.....	D9/452 X
3,480,172	11/1969	Shine	.....	D9/434 X
4,514,248	4/1985	Cummings	.....	215/232
4,550,842	11/1985	Cummings	.....	215/232
4,981,229	1/1991	Lanham	.....	D9/435 X

*Primary Examiner*—Alan P. Douglas  
*Assistant Examiner*—Robert M. Spear  
*Attorney, Agent, or Firm*—Patrick J. Pinto


[57] **CLAIM**

The ornamental design for a status indicating and tamper evident closure, as shown and described.

**DESCRIPTION**

FIG. 1 is a top plan view of a status indicating and tamper evident closure, showing my new design; FIG. 2 is a rear elevational view thereof; FIG. 3 is a front elevational view thereof; FIG. 4 is a right-side elevational view thereof; the left side elevational view being a mirror image of FIG. 4; FIG. 5 is a bottom plan view thereof; FIG. 6 is a perspective view showing the present invention after it has been adhesively attached to a cap of a vial or the like for covering an access port; and, FIG. 7 is a pictorial view of the present invention during removal of a tear away center portion to uncover the access port.

The discontinuous lines in FIGS. 1, 5, 6 and 7 indicate perforations and form a part of the claimed design.






FIG. 1




FIG. 5



FIG. 4



FIG. 2



FIG. 3




FIG. 6




FIG. 7