



US00D382147S

**United States Patent** [19]  
**Sandy**

[11] **Patent Number: Des. 382,147**  
[45] **Date of Patent: \*\*Aug. 12, 1997**

[54] **BROKEN PEDIMENT ENDCAP FOR  
SHELVING**

[76] Inventor: **Hal Sandy**, 4937 Glendale Rd.,  
Shawnee-Mission, Kans. 66205

[\*\*] Term: **14 Years**

[21] Appl. No.: **58,524**

[22] Filed: **Aug. 16, 1996**

[51] **LOC (6) Cl. .... 06-06**

[52] **U.S. Cl. .... D6/492; D6/494; D6/495;  
D25/126**

[58] **Field of Search** ..... D6/491, 492, 494,  
D6/495, 479, 509, 332; D25/58, 119, 120,  
122, 124, 126; 108/59, 60; 211/191, 153;  
52/239, 241, 243.1; 160/135

[56] **References Cited**

**U.S. PATENT DOCUMENTS**

D. 343,312 1/1994 Burdick et al. .... D6/495

D. 343,747 2/1994 Burdick et al. .... D6/495  
D. 376,282 12/1996 Sandy ..... D6/492  
4,263,761 4/1981 Kristoff ..... 52/241  
5,287,666 2/1994 Frascaroli et al. .... 52/239

**OTHER PUBLICATIONS**

Dahlstrom, 1969, p. 99, #2577 at top.

*Primary Examiner*—Janice E. Seeger


[57] **CLAIM**


The ornamental design for a broken pediment end cap for shelving, as shown and described.

**DESCRIPTION**

FIG. 1 is a perspective view;  
FIG. 2 is a side view, left view mirrors right;  
FIG. 3 is a back view;  
FIG. 4 is a front view;  
FIG. 5 is a top view; and,  
FIG. 6 is a bottom view.

**1 Claim, 3 Drawing Sheets**







*Fig. 1*



*Fig. 2*



*Fig. 3*



*Fig. 4*



*Fig. 5*



*Fig. 6*