



US00D580297S

(12) **United States Design Patent**
Dupureur

(10) **Patent No.:** **US D580,297 S**

(45) **Date of Patent:** **** Nov. 11, 2008**

(54) **CRACKED TEAPOT WITH A SCENE INSIDE**

(76) **Inventor:** **James Dupureur**, 1421 SE. 34th Ter.,
Cape Coral, FL (US) 33904

(**) **Term:** **14 Years**

(21) **Appl. No.:** **29/248,271**

(22) **Filed:** **Aug. 7, 2006**

(51) **LOC (8) Cl.** **11-02**

(52) **U.S. Cl.** **D11/131**

(58) **Field of Classification Search** D11/131-142,
D11/157-164, 184; D7/322, 321, 312, 313,
D7/300; 220/475; 222/472, 475, 475.1;
D21/525

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

2,135,410	A *	11/1938	Ottoson	222/129
2,284,087	A *	5/1942	Ferguson	99/295
D272,884	S *	3/1984	Seibel	D7/321
D308,796	S *	6/1990	Thurlow et al.	D7/322
D308,798	S *	6/1990	Ancona et al.	D7/322
D407,943	S *	4/1999	Chen	D7/322

D478,768	S *	8/2003	Belton	D7/322
6,648,725	B2 *	11/2003	Chan	446/479
D486,989	S *	2/2004	Bodum	D7/321
D502,838	S *	3/2005	Ancona	D7/321

* cited by examiner

Primary Examiner—Louis S Zarfaz

Assistant Examiner—Michelle E Wilson

(74) *Attorney, Agent, or Firm*—Hankin Patent Law, APC;
Marc E. Hankin

(57) **CLAIM**

The ornamental design for a cracked teapot with a scene inside, as shown and described.

DESCRIPTION

FIG. 1 is a side view of a cracked teapot with a scene inside.


FIG. 2 is a front view of a cracked teapot with a scene inside.

FIG. 3 is a back view of a cracked teapot with a scene inside;
and,

FIG. 4 is a top view of a cracked teapot with a scene inside.

The broken lines depict unclaimed environmental subject matter.

1 Claim, 4 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4