



US00D623824S

(12) **United States Design Patent**
Pendleton

(10) **Patent No.:** **US D623,824 S**

(45) **Date of Patent:** **** Sep. 14, 2010**

(54) **SAFE**

(75) Inventor: **Bruce Pendleton**, Loganville, GA (US)

(73) Assignee: **Pendleton Safe Company**, Loganville, GA (US)

(**) Term: **14 Years**

(21) Appl. No.: **29/352,397**

(22) Filed: **Dec. 21, 2009**

(51) **LOC (9) Cl.** **25-02**

(52) **U.S. Cl.** **D99/28; D99/43; D6/432**

(58) **Field of Classification Search** D99/28,
D99/43, 99; D6/432, 438, 441, 448, 457,
D6/470, 510; 109/7, 25, 38-39, 45, 47-48,
109/50, 59 R, 70, 71, 77; 211/4, 64; 312/135,
312/215, 297, 305, 409

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D586,525 S * 2/2009 Pendleton D99/28
D598,175 S * 8/2009 Pendleton D99/28

* cited by examiner

Primary Examiner—Lisa P Lichtenstein

(74) *Attorney, Agent, or Firm*—Brient Intellectual Property Law, LLC

(57) **CLAIM**

The ornamental design for a safe, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of a safe according to an embodiment of the present design with a door, door hinges, a combination entry keypad, and a handle assembly shown in broken lines.

FIG. 2 is a front elevation view of the safe of FIG. 1 with the door, door hinges, combination entry keypad, and handle assembly shown in broken lines.

FIG. 3 is a rear elevation view of the safe of FIG. 1.

FIG. 4 is a right side elevation view of the safe of FIG. 1 with the door hinges, handle assembly, and combination entry keypad shown in broken lines.



FIG. 5 is a left side elevation view of the safe of FIG. 1 with the door hinges, handle assembly, and the combination entry keypad shown in broken lines.

FIG. 6 is a top plan view of the safe of FIG. 1 with the handle assembly, door hinges, and the combination entry keypad shown in broken lines; and,

FIG. 7 is a bottom plan view of the safe of FIG. 1 with the handle assembly, door hinges, and the combination entry keypad shown in broken lines.

The broken lines shown in FIGS. 1 through 7 illustrate portions of the safe that form no part of the claimed design.

1 Claim, 6 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7