



US00D794714S

(12) **United States Design Patent**
Jones

(10) **Patent No.:** **US D794,714 S**

(45) **Date of Patent:** **** Aug. 15, 2017**

- (54) **WARNING SIGN**
- (71) Applicant: **David Jones**, Melrose Park, IL (US)
- (72) Inventor: **David Jones**, Melrose Park, IL (US)
- (73) Assignee: **ALOIS BOX CO., INC.**, Melrose Park, IL (US)

- 3,001,906 A * 9/1961 Capella B31D 1/021
156/201
- 4,128,357 A * 12/1978 Barth B28B 3/021
404/41
- 5,379,538 A * 1/1995 Osborne G09F 3/10
156/227
- D377,270 S * 1/1997 Neal D5/53
- 2012/0047784 A1* 3/2012 St. Denis G09F 19/22
40/607.13

(**) Term: **15 Years**

* cited by examiner

(21) Appl. No.: **29/536,855**

Primary Examiner — Mary Ann Calabrese

(22) Filed: **Aug. 20, 2015**

(74) *Attorney, Agent, or Firm* — Justin Lampel

(51) **LOC (10) Cl.** **20-03**

(52) **U.S. Cl.**

USPC **D20/40; D20/29; D10/109.1**

(58) **Field of Classification Search**

USPC D20/10, 19, 22–29, 40, 99; D10/109.1,
D10/113.4

CPC G09F 1/00; G09F 1/02; G09F 2003/0208;
G09F 2003/03; G09F 2003/0266; G09F
2003/0267; G09F 7/00; G09F 9/00; G09F
13/00; G09F 19/22; G09F 23/10; G09G
3/00; G09G 3/08; G09G 3/10; B31D
1/021; B31D 29/00

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

- 361,603 A * 4/1887 Wheeler B32B 29/00
428/43
- 857,778 A * 6/1907 Wittstrin G09F 3/00
40/639
- 2,636,297 A * 4/1953 Johnson G09F 3/10
156/253
- 2,799,104 A * 7/1957 Griesinger G09F 3/10
40/638

(57) **CLAIM**

The ornamental design for an warning sign, as shown and described.

DESCRIPTION

FIG. 1 is a perspective view of the warning sign in the flat orientation;

FIG. 2 is a top view of the warning sign;

FIG. 3 is a bottom view of the warning sign;

FIG. 4 is a front view of the warning sign;

FIG. 5 is a back view of the warning sign;


FIG. 6 is a side view of the warning sign;

FIG. 7 is a side view of the warning sign; and,

FIG. 8 is a perspective view of the assembled device on a shipping container.

In the drawings, the dotted broken lines represent perforations. The dashed broken lines showing text on the warning sign and a shipping container illustrate environment and form no part of the claimed design.

1 Claim, 5 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8