



US00D805612S

(12) **United States Design Patent** (10) **Patent No.:** **US D805,612 S**
Mursu et al. (45) **Date of Patent:** **** Dec. 19, 2017**

(54) **HOSE FITTING**

(71) Applicant: **Rockler Companies, Inc.**, Medina, MN
(US)

(72) Inventors: **Emily Anne Mursu**, Plymouth, MN
(US); **Daniel Lloyd Wenning**,
Minnetonka, MN (US)

(73) Assignee: **Rockler Companies, Inc.**, Medina, MN
(US)

(**) Term: **15 Years**

(21) Appl. No.: **29/603,000**

(22) Filed: **May 5, 2017**

Related U.S. Application Data

(62) Division of application No. 29/548,644, filed on Dec.
15, 2015.

(51) **LOC (10) Cl.** **23-01**

(52) **U.S. Cl.**
USPC **D23/259**; D32/25

(58) **Field of Classification Search**

USPC D23/213, 223, 259–266; D32/14, 25,
D32/31–33, 39; 137/798; 138/122, 131,
138/133; 285/335; 15/359, 371, 373,
15/417

CPC F16L 33/227; F16L 33/22; F16L 29/007;
F16L 31/00; F16L 25/0018; A47L 9/06;
A47L 9/062; A47L 9/0633; A47L 9/24

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D300,574 S * 4/1989 Smith D32/31
D314,848 S * 2/1991 Foldes D32/31

D417,534 S * 12/1999 Holston D32/31
D638,918 S * 5/2011 Grether D23/263
D652,917 S * 1/2012 Hill D24/129
D678,028 S * 3/2013 Rosenau D8/70
D679,784 S * 4/2013 Meyer D23/262
D683,918 S * 6/2013 Erlich D32/25
D687,195 S * 7/2013 Sell D32/21
D698,107 S * 1/2014 Selby D32/25
D712,013 S * 8/2014 Mather D23/259
D718,009 S * 11/2014 Sun D32/31
2011/0142561 A1 * 6/2011 Hahn B23Q 11/0046
408/56

* cited by examiner

Primary Examiner — Eric L Goodman

Assistant Examiner — Amy C Wierenga

(74) *Attorney, Agent, or Firm* — James L. Young;
Westman, Champlin & Koehler, P.A.


(57) **CLAIM**

The ornamental design for a hose fitting, as shown and
described.

DESCRIPTION

FIG. 1 is a perspective view of a hose fitting;
FIG. 2 is a front view of the hose fitting of FIG. 1;
FIG. 3 is a rear view thereof of the hose fitting of FIG. 1;
FIG. 4 is a side view of the hose fitting of FIG. 1 (as taken
from the left of FIG. 2);
FIG. 5 is a side view of the hose fitting of FIG. 1 (as taken
from the right of FIG. 2);
FIG. 6 is a top view of the hose fitting of FIG. 1; and,
FIG. 7 is a bottom view of the hose fitting of FIG. 1.
The broken lines shown in the drawings depict portions of
the hose fitting that form no part of the claim.

1 Claim, 6 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7