



US00D819070S

(12) **United States Design Patent** (10) **Patent No.:** **US D819,070 S**
Nanjappan et al. (45) **Date of Patent:** **** May 29, 2018**

(54) **DISPLAY SCREEN OR PORTION THEREOF WITH GRAPHICAL USER INTERFACE**

(71) Applicant: **OTIS ELEVATOR COMPANY**,
Farmington, CT (US)

(72) Inventors: **Ezhil Nanjappan**, Farmington, CT
(US); **Lara Siopis**, West Hartford, CT
(US); **Ashley Chapman**, Plainville, CT
(US)

(73) Assignee: **OTIS ELEVATOR COMPANY**,
Farmington, CT (US)

(**) Term: **15 Years**

(21) Appl. No.: **29/585,298**

(22) Filed: **Nov. 22, 2016**

(51) **LOC (11) Cl.** **14-04**

(52) **U.S. Cl.**
USPC **D14/486**

(58) **Field of Classification Search**
USPC D14/485-495
CPC G06F 3/04817; G06F 3/0482
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

9,081,746 B1 * 7/2015 Helter G06F 15/177
D751,594 S * 3/2016 Fedorov D14/486

D786,890 S * 5/2017 Kohan D14/485
2014/0164893 A1 * 6/2014 Pariente G06F 17/30896
715/207
2017/0185248 A1 * 6/2017 Lee G06F 3/0482

OTHER PUBLICATIONS

Examination Report; European Community Application No.
004009462-0001; Dated Jul. 10, 2017; 4 Pages.

* cited by examiner

Primary Examiner — Richelle G Shelton

(74) *Attorney, Agent, or Firm* — Cantor Colburn LLP

(57) **CLAIM**


The ornamental design for a display screen or portion thereof with graphical user interface, as shown and described.

DESCRIPTION

The FIGURE is a front view of a display screen or portion thereof with graphical user interface showing our new design.

The broken lines showing the display screen or portion thereof and portions of the graphical user interface form no part of the claimed design.

1 Claim, 1 Drawing Sheet



CUSTOMER QUALITYJUNI SMITH

MECHANICAL AUDIT REPORT FOR
PARKVIEW LINDSEY
HOTEL BUILDING EAST
123 ST. SHELBYVILLE, KY 40381

ADTOR
CEDAR KNOLLS
AUDIT DATE
18 APR 2018
UNIT NUMBER
3212

OVERALL IMPRESSIONS

ROCK QUALITY

PAUSE

LEVELING

RIDER EXPERIENCE CHECKS

CAR
-CAR FLOOR IS INTACT
-CAR WALLS ARE IN GOOD SHAPE

DOORS
-DOORS ARE UNLATCHED
-DOORS ARE ON TRACK
-DOORS ARE FUNCTIONING NORMALLY

COP
-BUTTON LIGHTS ARE ALL WORKING
-NO BUTTONS ARE STICKING

SAFETY CHECKS

ROCK
-CAR FLOOR IS INTACT
-CAR WALLS ARE IN GOOD SHAPE

DOORS
-DOORS ARE UNLATCHED
-DOORS ARE ON TRACK
-DOORS ARE FUNCTIONING NORMALLY

TOP OF CAR ROOF
-BUTTON LIGHTS ARE ALL WORKING
-NO BUTTONS ARE STICKING

WALKING DECKING CHECKS

WALKING DECK
-CAR FLOOR IS INTACT
-CAR WALLS ARE IN GOOD SHAPE

FEET
-DOORS ARE UNLATCHED
-DOORS ARE ON TRACK
-DOORS ARE FUNCTIONING NORMALLY