



US00D832407S

(12) **United States Design Patent**
Karnegie

(10) **Patent No.:** **US D832,407 S**

(45) **Date of Patent:** **** Oct. 30, 2018**

(54) **TUB DRAIN COVER**

D691,244 S * 10/2013 Ho D23/261
D725,752 S * 3/2015 Bargiel D23/261
D743,509 S * 11/2015 Traub D23/261

(71) Applicant: **Juka Innovations Corporation**,
Farmingdale, NY (US)

(72) Inventor: **Serge Karnegie**, Glen Cove, NY (US)

(73) Assignee: **JUKA INNOVATIONS CORPORATION**, Farmingdale, NY (US)

(**) Term: **15 Years**

(21) Appl. No.: **29/627,347**

(22) Filed: **Nov. 27, 2017**

(51) **LOC (11) Cl.** **23-01**

(52) **U.S. Cl.**
USPC **D23/261**

(58) **Field of Classification Search**
USPC D23/259–261, 208–210; D7/399, 400;
D21/597, 599; 4/286–287, 292–293, 295
CPC E03C 1/03; E03C 1/22; E03C 1/23; E03C
1/26; E03C 1/262; E03C 1/264
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

1,494,882 A * 5/1924 Barger E03C 1/264
4/292
1,950,817 A * 3/1934 Rossman E03C 1/264
4/291
D248,134 S * 6/1978 Shames D23/260
D336,948 S * 6/1993 Frankel D23/261
D379,403 S * 5/1997 Jones D23/261
D597,181 S * 7/2009 Jones D23/260
D662,573 S * 6/2012 Rogalski D23/261
D673,247 S * 12/2012 Eylon D23/261
D680,628 S * 4/2013 Houck D23/260
D686,707 S * 7/2013 Ychie D23/261

OTHER PUBLICATIONS

StopShroom Universal Stopper Plug Cover for Bathtub, Bathroom, and Kitchen Drains, Aqua, Earliest Review Mar. 27, 2018, [Visited Online Jul. 15, 2018], https://www.amazon.com/StopShroom-Universal-Stopper-Bathtub-Bathroom/dp/B07B7VNV7V/ref=sr_1_84_sspa?ie=UTF8&qid=1531677707&sr=8-84-spons&keywords=drain+stopper+bath.*

* cited by examiner

Primary Examiner — Eric L Goodman
Assistant Examiner — Amy C Wierenga


(57) **CLAIM**

The ornamental design for a tub drain cover, as shown and described.

DESCRIPTION

FIG. 1 is a top right perspective view of a tub drain cover showing my new design;
FIG. 2 is a top left perspective view thereof;
FIG. 3 is a bottom left perspective view thereof;
FIG. 4 is a front view thereof;
FIG. 5 is a back view thereof;
FIG. 6 is a top view thereof;
FIG. 7 is a bottom view thereof;
FIG. 8 is a left view thereof; and,
FIG. 9 is a right view thereof.
The broken lines shown in FIGS. 1-4 and 6-9 illustrate portions of the tub drain cover that form no part of the claim.

1 Claim, 9 Drawing Sheets






FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9